Howard Road Historic District Lloyd Sharp House 1010 Howard Road Washington District of Columbia

HABS No. DC-395-D

## **PHOTOGRAPHS**

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey
National Park Service
Department of the Interior
Washington, DC 20013-7127

Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HARS IX, WASH, 441-

## ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
District of Columbia			Washington	
HISTORIC NAME OF STRUCTURE (INCLUOE SOURCE FOR NAME)				HABS NO.
Lloyd Sharp House (building permit)			DC-395-D	
SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 1010 Howard Road, Washington, D.C.				
DATE OF CONSTRUCTION (INCLUOE SOURCE)  ARCHITECT(S) (INCLUOE SOURCE)			7)	
		James S. Steward, builder (permit)		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The Sharp house is representative of "builders' spec" houses built in Howard Road on lots subdivided out of original Barry's Farm lots in the late 19th and early 20th centuries. Characteristic features include narrow, side-hall plan and use of stock moldings and other architectural elements. STYLE (IF APPROPRIATE)				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Balloon frame on brick foundation; exterior covered with synthetic shingle siding.				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  Two stories, approx. 18' x 36', flat roof sloping down at rear; two bay facade and full-width front porch (see sketched floor plan)				
EXTERIOR FEATURES OF NOTE Porch has factory-turned posts; metal cornice with brackets and elongated, stylized dentils extends across facade; 2/2 wood d.h.s. in flat surrounds; glazed transom light over entrance.				
INTERIOR FEATURES OF NOTE (OESCRIBE FLOOR PLANS, IF NOT SKETCHEO) Door and window surrounds have simple moldings and bulls—eye corner blocks; a wide plaster arch separates front and rear parlors on first floor				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES				
1901-second floor added above kitchen at rear				
date unknown- exterior covered with synthetic shingle siding				
PRESENT CONDITION AND USE Building is vacant, in poor condition, and has been vandalized.				
OTHER INFORMATION AS APPROPRIATE Documentation prepared by Louis Berger & Associates, Inc.,				
for the Washington Metropolitan Area Transit Authority in compliance with a Memorandum of Agreement with the Advisory Council on Historic Preservation.				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
D.C. Building permits: #1229, 3/12/1894; #597, 10/31/1901; determined				
eligible for the National Register as part of the Howard Road Historic District.				
COMPILER, AFFILIATION				DATE
M.H. Boy	vers, Louis Be:	rger & Associates	s, Inc.	6 November 1984

SECOND FLOOR



